



6 Month inspection shows continued deterioration of the anode rod.

The tank itself shows no added signs of corrosion even at the bi-metal connections.



AUTHOR				
DATE nov 08	SHEET	1	OF	1
REVISION				